ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	12	Shettihalli
Street ID	**Street Name**	**Significant Landmark**
W0140, W0138, W0071, W0054, W0039	3rd Crs, 2nd Crs, NA	ABBIGERE TANK
Segment No.	**Total Length (m)**	
12/S-W0140/S112341	132.21	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	54.53	77.524289	13.074986	77.524779	13.074877	W0667	DEAD END
2	30.33	77.527077	13.071795	77.527351	13.071854	W0667	DEAD END
3	47.35	77.527215	13.071658	77.527641	13.071751	W0039	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
PROVIDING IMPROVEMENTS TO ROADS AND DRAINS AT SHESHAGIRI LYT BALANCE PORTION AT ABBIGERE NEAR ABBIGERE TANK	1500000	2015
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Others	ROAD AND DRAINS
Tender	**Work Details**	**Job No. / Work Code**
Tender		012-15-000016
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/248/14-15	18/02/2015	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
		No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
PUTTARAJU		0.00
Phone No.	**E-Mail ID**	
9837373635		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		ravi

Date of Inspection	Remarks
13/02/2016	

Category	Image	Photo Remark
Drain Condition		Location was not determined.
Road Condition		Location was not determined.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	SIDDEGOWDA	13/02/2016	14/03/2016	COMPLETED
EE	JOGI SIDDEGOWDA	13/02/2016	14/03/2016	COMPLETED
AEE	JAYALINGAPPA	13/02/2016	14/03/2016	COMPLETED
AE	RAVI	13/02/2016	14/03/2016	COMPLETED
AE	RAVI	13/02/2016	14/03/2016	COMPLETED

Zone: DASARAHALLI **Ward No:** 12 **Ward Name:** Shettihalli **Street ID:** W0140, W0138, W0071, W0054,